son no PRESENT:

ERPT FROM THE MINUTES OF THE REGULAR SESSION OF THIRD SANGGUNIANG PANLUNGSOD NG ORMOC HELD A T

ITS SESSION HALL ON SEPTEMBER 17, 1986

Hon. Benjamin B. Lladoc, OIC, Office of the Vice-Mayor Presiding Officer

Hon. Gregorio A. Yrastorza, Jr., Kagawad, Floor Leaden Kagawad Kagawad

Hon. Vicente V. Redoña,

Hon. Arnulfo C. Salazar,

Hon. Rodolfo L. Rivilla, Jr.,

Hon. Avelina D. Subingsubing,

Hon. Antonio C. Sumaljag,

Hon. Romeo M. Hermosilla, ABC President.

ABSENT:

Hon. Laureano J. Suan,

Hon. Ma. Emily C. Codilla, FKB President,

Kagawad Kagawad

Kagawad

KagawaduF[

Kagawad 6 00

KalkawantE

Kagawad

RESOLUTION ON. 81

A RESOLUTION INVITING THE ATTENTION OF THE CITY TREASURER TO TAKE NOTE OF THE REPORT OF THE CITY ENGINEER REGARD ING THE DAMAGE OF THE TOYOTA LAND CRUISER WITH PLATE NO. HAG-248 SO THAT THE CITY GOVERNMENT COULD REQUEST THE GOVERNMENT SERVICE INSURANCE SYSTEM (GSIS) TO PAY THE REPAIR OF THE SAME AND FORTHWITH IF THERE WILL BE A WINNING BIDDER TO UNDERTAKE THE REPAIR IT MUST BE IN ORMOC CITY, WHO IS A DULY ACCREDITED SHOP.

"WHEREAS, we are in receipt of the report of the City Engineer dated September 12, 1986 regarding the damage of the Toyota Land Cruiser with Plate No. HAG-248, QUOTED HEREUNDER verbatim, to wit:

> 'Ministry of Public Works and Highways REGION VIII OFFICE OF THE CITY ENGINEER Ormoc City

> > September 12, 1986

Report on damaged parts of Toyota Land Cruiser bearing plate No. HAG-248:

Hard top (fiber glass) was broken, needs replacement,

Right side window glass and right side corner glass were

broken, need replacement, 1 pcs - hanger w/ pin and bushing rear right, front, was defective, need replacement,

2 pcs. - from shackle w/ pin and bushing were defective,

need replacement, 1 pc .- spring assy. front was defective, needs replacement,

2 pcs. - tire w/ inner tube were defective, need replacement,

1 pc. - signal light assy., front, was broken, needs replace-7. ment,

2 pcs. - side mirror were broken, need replacement,

Right side body, door and fender were badly damaged, needs general repair and repainting w/ same color,

10. Bumper and chassis were disaligned. need repair and realign-

11. Front seat frame defective, needs repair,

12. 1 unit - Car Stereo and antenna were defective, needs repair,

13. 1 pc. - Car stereo speaker was broken. needs replacement.

PREPARED BY:

(SGD) SOLOMON W. RITA Mechanical Engineer

NOTED:

(SGD) RUBEN C. PENSERGA City Engineer

"WHEREAS, if there will be a winning bidder to undertake the repair of the damaged Toyota Land Cruiser it must be in Ormoc City, who is a duly accredited shop;

"NOW, THEREFORE, on motion of Kagawad Sumaljag, seconded by Kagawad Subingsubing; be it

"RESOLVED, to invite the attention of the City Treasurer to take note of the report of the Mechanical Engineer, City Engineer Office regarding the damage of the Toyota Land Cruiser with Plate No. HAG-248 so that the city government could request the Government Service Insurance System (GSIS) to pay the repiar of the same and forthwith, if there will be a winning bidder to undertake the repair of the damaged Toyota Land Cruiser it must be in Ormoc City, who is a duly accredited shop;

"RESOLVED, FURTHER, to furnish a copy of this resolution each to the Branch Manager, Government Service Insurance System, Tacloban City, the City Treasurer and the City Engineer, both in Ormoc City;

"CARRIED UNANIMOUSLY".

I HEREBY CERTIFY to the correctness of the above-quoted resolution.

EMMANUEL ANTHONY C. SABELINO Secretary

ATTESTED:

BENJAMIN B. LLADOC

OIC, office of the Vice-Mayor Presiding Officer

APPROVED:

EMETERION. LARRAZABAL OIC, City Mayor's Office

ATTESTED AS APPROVED:

CELESTING L. LARRAZABAL Secretary to the Mayor